



## Minor improvements and bugfixes

- New driver for R&S FSH4
- New driver for R&S ZVL in VNA mode
- New driver for Agilent Real time spectrum analyzers MXA and PXA.
- New driver for Agilent FieldFox.
- Optimized all drivers for speed when using long probe correction factors.
- Improved picture contrast when overlaying photo i ViewScan.
- Improved functionality on transparent white in ViewScan.
- Improved functionality on the drivern for R&S FSEA - Added SkipReset and SweepTime
- Added a small delay in the driver for HP8560E
- Removed several SA drivers and replaced them with Visa versions. - Agilent E444x, AgilentMXA, R&S ESL..., R&S FSL, R&S FSL (Visa)
- Bugfix: Calibrate to beacon - Side length sometimes contained wrong decimal character.
- Generic R&S driver tested with FSP.
- Small improvement in the driver for Advantest R3261
- Small improvements in Scanner drivers for network (HR1E, HR41E, HR43EB, RSE321, RSE642, RSE644)
- Bugfix: "Also save MultiScan measurements as TXT-files" didn't work in batch mode
- Bugfix: Drivers for Agilent N9320A and B didn't apply probe correction on trace data.
- Bugfix: "EditPassword.PasswordChar: Invalid property value" at startup on some asian windows. The bug was introduced in version 2.9.0.